



ENVIRONMENTAL & REGULATORY SERVICES  
PECFA  
P. O. Box 8044  
Madison, Wisconsin 53707-8044  
TDD #: (608) 264-8777  
[www.commerce.state.wi.us](http://www.commerce.state.wi.us)

Tommy G. Thompson, Governor  
Brenda J. Blanchard, Secretary

## Wisconsin Department of Commerce PECFA Program

### Questions & Answers

**Bid Round number**      **07**  
**PECFA number:**        **54241-9999-00**  
**BRRTS number:**       **03-36-001966 & 02-36-000584**  
**Site Owner:**            **Mid Lakes FS Cooperative; Attn: Mr. Norm Johnson**  
**Site Name:**             **Mid Lakes FS Cooperative**  
**Site Address:**          **600 Forest Home Drive, Francis Creek, WI**

**Project Manager:**                      **Keld B. Lauridsen**  
**Project Manager address:**           **1125 North Military Ave, P.O. Box 10448,**  
   **Green Bay WI 54307-0448**  
**Project Manager phone:**             **(920) 492-5921**  
**Project Manager e-mail address**     [Laurik@dnr.state.wi.us](mailto:Laurik@dnr.state.wi.us)

<b>Bid Announcement Date</b>	<b>Wednesday, March 15, 2000</b>
<b>Questions or requests for information must be submitted in writing and received by:</b>	<b>Friday, 03/31/00 by 16:00 CST</b>
<b>Responses to the questions will be posted (and if requested, sent in writing) by:</b>	<b>Friday, 04/21/00</b>
<b>Bid End Date and Time:</b>	<b>Monday, 05/01/00 by 12:00 CST</b>

Q1:    What caused the significant water level changes in wells after 5/96, except for the wells with recordable free product?

A1:    Assumed to be naturally occurring groundwater fluctuations.

Q2:    Is the deep aquifer affected by utility corridor?

A2:    It is required to assess the potential for contaminant migration via utility trenches prior to obtaining closure.

- Q3: Are there any potable wells in the area not defined in the bid doc? If so how many and where are they located?
- A3: The Site Investigation Report (dated August 1998) identified the location of 10 water supply wells in the general area of the site.
- Q4: Is there any additional groundwater sampling data available for this site?
- A4: Groundwater sample collected from off site temporary monitoring well on December 9, 1999 (refer to Supplemental Site Investigation Report dated January 2000).
- Q5: Does the Department feel that the vertical extent is properly defined since there are no Piezometers on the site?
- A5: Piezometers may be appropriate to define the vertical extent.
- Q6: Is the bidder to include costs for the investigative waste remaining on-site?
- A6: This should be the responsibility of the consultant conducting the site investigation. However, it probably could be included with this bid for minimal cost. The disposal cost of the existing investigative waste would be insignificant if the proposed remedial action involves source removal.
- Q7: Is the bidder to include non PECFA related costs due to the incidental remediation and waste disposal of the commingled pesticide and fertilizer contamination?
- A7: No.
- Q8: Has a PECFA approved breakdown of non eligible cost attributed to non eligible product (pesticides) been established?
- A8: This is determined on a case by case basis.